

## All-building investigation progress

		Total to be investigated	Investigation commenced	Investigation progress rate	No deficiencies confirmed	Deficiencies confirmed			
						No parting wall in entire attic or space above ceiling	No parting wall above balcony or hallway	No parting wall in space above ceiling of middle floors	Partial deficiencies (gaps, holes made by electric wires, etc.)
						No. of buildings	No. of buildings	No. of buildings	No. of buildings
Top priority	Nail series	918	185	20.15%	16	169	0	0	0
	Subject properties (6 series)	13,791	711	5.16%	336	8	91	22	109
	Series other than the above	23,152	-	-	-	-	-	-	-
	Total	37,861	896	2.37%	352	177	91	22	109