Overview of apartment series subject to top priority investigations As of June 27, 2018 Roof-Series name / Period 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2008 2009 2007 type Jan 1994 - Dec 1995 Sections to be investigated **Gold Nail** (1) ♦①Parting wall in attic (presence) **GN, NGN New Gold Nail** ◆②Roof space of each floor (parting wall) **\**2 Wooden framing (2x4), 2 floors Gable-type (with attic) Jan 1996 - Apr 2000 Sections to be investigated 1 **Gold Residence** ◆①Parting wall in attic (presence) ◆②Parting wall in roof space of each floor **\**2) Steel (braced panel), 2-3 floors ♦ Parting wall in eaves (hallway, balcony) \*only semi-fireproof structures Jul 1997 - Mar 2000 Sections to be investigated (1)**New Silver Residence** ◆①Parting wall in roof space of each floor ♦ Parting wall in eaves (hallway, balcony) \*after Ver3 Wooden post & beam (panel), 2 floors Jan 1998 - May 2000 Sections to be investigated **New Gold Residence** ♦1)Parting wall in roof space of each floor NGR ♦ ②Parting wall in eaves (hallway, balcony) \*only snow-areas Steel (braced panel), 2 floors Apr 1999 - Jun 2000 Sections to be investigated **Special Steel** 1 ♦①Parting wall in roof space of each floor Residence ♦ ②Parting wall in eaves (hallway) Steel (braced panel), 2 floors Jan 2000 - Aug 2000 Sections to be investigated **Better Steel** 1 Flat-roof ♦①Parting wall in roof space of each floor Residence (without attic) **(1)** Steel (braced panel), 2 floors Jul 2000 - Mar 2009 Sections to be investigated **Con Grazia**  $^{\circ}$ ♦①Parting wall in roof space of each floor Steel type ♦②Parting wall in eaves (hallway, balcony)  $\overline{\mathbb{T}}$ Steel (braced panel), 2-3 floors Jul 2000 - Mar 2009 Sections to be investigated **Con Grazia** 1 ◆①Parting wall in roof space of each floor Wooden type (Standard) **FCW** ♦②Parting wall in eaves (hallway) 1 Wooden post & beam (panel), 2 floors Jul 2000 - Mar 2009 Sections to be investigated Con Grazia

Concerning tenant evacuation during repair works... Sections to be investigated ◆: evacuation necessary ♦: evacuation unnecessary \*"Sections to be investigated" and "tenant evacuation" may change due to building situations

◆①Parting wall in roof space of each floor

Six series

Wooden type (Hokkaido)

Wooden traditional post & beam (panel), 2 floors